



Webinar: Avoid Costly Problems

Assessing and Restoring Complex Building Envelope Systems

Agenda

Building the Team for Project Success Chris Barger Senior Construction Consultant, CCA

Case Study at White Cliffs Condo II Glenn Grassi

President, White Cliffs Community II Association

3 Par

2

Panel Discussion Eric Churchill, Executive Vice President, SPS

Greg Hoyt, Senior Structural Engineer, CCA

Building the Team for Project Success




The Project Team






The Project Team





The Project Team





Case Study at White Cliffs Condo II



White Cliffs Country Club

Located in **Plymouth Massachusetts** at the edge of a 140 foot high cliff overlooking Cape Cod Bay and the Atlantic Ocean.

There are **367 condo units** divided into **6 condominium associations** controlled by separate condo boards



Condominium II Association – Twin Woods

Condo II consists of three buildings, 8 units in each

The units were constructed in 1985 and are **35 years old**

Winter storm winds can reach 90 miles per hour and challenge the integrity of the buildings



Board of Trustees

Five-member Board of Trustees

Little or no experience in maintenance or construction







Interior ceiling and wall stains

Original Construction 1985

- Poor quality
 - Roofing had no membrane or step flashing integrated with siding
 - Windows were not properly sized to the rough openings
 - Windows were not properly sealed or insulated
 - Deck attachments were not properly sealed and waterproofed



All Things Change In Time

Over the years, **leaks have developed** causing severe interior damage

Window seals have dried up and crumbled

Window and door mechanisms have **corroded and rusted shut** due to the salt air

Nail heads securing the siding have **rusted away**






Historical Mistakes

- 1995 a vinyl siding layer was place over the origin wood clap board
- 2003 a second layer of roof was added to the first without being integrated with the siding





Complex Roof Configuration

Each building has 65 individual roof sections

There are 200+ edges of roof that intersect walls and chimneys

The waterproof material for the roof must continue onto the walls

Adding the **second roof at a cost of \$95,000** did nothing to resolve the edge leaks



Proper Integration Between Roof and Siding



Waterproof membrane <u>must transition</u> from horizontal to vertical surfaces and integrate with the wall's weather resistant barrier.

Proper Sealing of Walls





Inside and outside wall corners are sealed with taped

House wrap is applied as a continuous barrier around corners

Structures Deteriorate Due to Poor Maintenance

Wooden deck structures have deteriorated with age

Steel doors are constantly rusting




Direct Impact on Homeowner

Ice dams are a constant cause of interior ceiling and wall damage



Yearly Maintenance Costs Kept Raising





Strategic Approach

Research previous projects at White Cliffs

- Meet with SPS to discuss a step by step approach to the solution
- \checkmark

Meeting with unit owners and discuss the plan

Secure bank financing

- Team up with an architectural engineering company, CCA
 - Permits, Scope of work definition, Price verification and Structural modification



Bring in a legal team to review contracts



Acquire builders risk insurance



The Finished Product

Modern materials are now the standard

- Windows are made entirely of vinyl and are energy efficient windows with stainless steel hinges
- Composite doors that will not rust
- High quality rubberized self-sticking roof underlayment provide a water-tight seal
- Composite decking and vinyl railings do not require painting
- All trim work is made of low maintenance composite material
- All screws holes are sealed with composite plugs
- Vinyl siding that is resistant to high winds

Not one exterior surface requires painting



Panel Discussion



3


How do we know we have a problem if we can't see it?

What if everything looks good?





Potential failure (thermographic imagery)



Verified envelope failure


How do we address ongoing failures?



Previous repair performed, Note: different shades of vinyl siding.



Major rot due to leaking window and lack of rough opening flashing.



Resulting sheathing and framing rot due to lack of flashing at window.

What can happen if we do not investigate?





What should we consider if we wanted to complete a project in phases?

What are the most common failures at the junction of the envelope and decks or balconies?

Why is it a good idea to have an engineer on the project?

What happens if we wait and build up reserves to pay for the work?

What's the best way to convince the condo community to buy into an envelope project?

What is the best way to bring homeowners, who are responsible for windows & doors, into funding the restoration project of the building?

How can we be sure the projected scope is accurate?





What Happens Next?



Email with slides, recording, an Envelope Project Checklist



If you need hands-on support, our experts can help you evaluate your envelope challenges:

- Roof, deck or balcony failures
- Water intrusion into the wall cavities
- Price verification and scope validation
- Bid process
- Construction management

Contact John Tripp, Director of Business Development, CCA (781) 301-5220; <u>jtripp@ccaco.com</u>